

H CURT

REQUIREMENTS FOR PROTECTIVE EQUIPMENT

1. All employees must wear seatbelts at all times while operating the vehicle.

2. All employees must wear proper PPE (hard hats, safety glasses, steel toe shoes, etc.) at all times while operating the vehicle.

OPERATIONAL PROCEDURES

1. All employees must follow the manufacturer's instructions and safety warnings for the vehicle at all times while operating the vehicle.

Continued on

